

Having trouble viewing this email? [Click here](#)

# heads UP

for this garment

INTERNATIONAL TEXTILE ANALYSIS LABORATORY

[Click here for a PDF of this newsletter](#)

## Bebe

RN#: 86017

Bebe Studio Inc.  
Distributor, Retailer  
400 Valley Dr.

Brisbane, CA 94005  
Ph. 1-877-232- 3777 or  
415-715-3939

[www.bebe.com](http://www.bebe.com)

May 18, 2009

**The garment:** A ladies wool/Tencel/nylon blend cream-colored coat with black leather buttons and ribbon trim. The care label states: "dry clean only" with no International code symbols.

**The problem:** During dry cleaning in perchlorethylene (perc), the black trim dye bleeds, resulting in transfer of color onto the white coat body in various areas.

**Who's responsible?** The manufacturer since the black leather trim was not able to withstand the recommended care instructions without dye disturbance.

**What to do:** This coat should be returned to the retailer or manufacturer.

Click image for a larger view



The black trim sections of this white coat could not withstand drycleaning without dye bleeding.

